

## Footpaths/PROW status of work ongoing as at 03.10.16

Date reported	Problem/details	Category	Action
10/08/2015	Poor condition of surface of PROW 1 Carnon Downs	PROW	Clerk emailed Cormac to request surface inspected, chased again on 10.12.15
17/08/2015	Poor condition of surface of PROW 1 Carnon Downs	PROW	Clerk given callers contact details to Cormac and requested surface be inspected. Update 17/09 Footpaths Officer advised she is arranging an inspection of the surface and will let me know the outcome, chased again on 10.12.15
01/08/2015	Tregye footpath 19, Tregye to Lower Tresithick, no footpath sign at junction with Tresithick Lane	PROW	Requested new sign from Cormac
2012	Happy Valley footpath 20, Lower Tresithick to Penpol Vale, steps from the stream to Penpol Vale in poor repair	PROW	Reported to Cormac for repair, being repaired asap COMPLETED BY CORMAC
01/08/2015	Tresithick Wood footpath 21, Lower Tresithick to Penpol, poor drainage at the top of the path has caused water cut out of surface	PROW	Reported to Cormac for repair
01/08/2015	Tregoose footpath 22, Lower Tresithick to Trengoose, waymarks required at junction with footpath 21	PROW	Requested new waymarkers from Cormac for Feock PC to install
01/08/2015	Mid Dev to Tregoose footpath 27, The field gate at the junction with FP 31 is locked and the alternative style is substandard	PROW	Reported to Cormac

01/04/2015	Tallack's Valley footpath 28, Tallacks Creek to the Point Road, the first stile is redundant and the second substandard	PROW	First stile now removed
01/04/2015	Higher Quay footpath 29, Carclew Terrace to Tank Hill and Quay Road. The original route of the footpath has been built over, a current undisputed route does not appear on the definitive map	PROW	Feock PC to register the undisputed route, paperwork received 01.12.15
01/08/2015	Tallack's Flats, footpath 29, Devoran Quay to Carnon Mine. The stepping stone stream crossings at Tallacks Creek and Carnon Mine are both in very poor condition	PROW	Feock PC to consider provision of additional stepping stones
01/08/2015	Footpath 29 at Carnon Mine the footpath signpost to the Beach has fallen over	PROW	Feock PC to reinstate signpost
01/08/2015	Penpol Pool, Penpol Bridge to Penpol Boatyard, footpath 46. The footpath is overgrown to single track in places	PROW	Feock PC to consider cutting back to a "family width" (Lengthsman) COMPLETED BY FEOCK PC
2012	Trolver Beach, Penpol Boatyard to Carnon Yard, footpath 59, no footpath signpost at Penpol Boatyard	PROW	Installation of steps and signposts being progressed by Cormac
18/08/2015	Surface of footpath 43, La Feock to Pill Lane needs attention as is very stony	PROW	Cormac inspected and advised surface satisfactory
17/09/2015	Broken footpath signpost at bottom of Rocky Lane, footpath 24/2 at junction with Tram Road (Devoran)	PROW	Reported to Cormac, added to their maintenance list
17/09/2015	Broken footpath signpost at bottom of footpath 28/1 at junction with the Tram Road (Devoran)	PROW	Reported to Cormac, added to their maintenance list
17/09/2015	Broken footpath signpost at start of footpath 46/2 at Harcourt the junction with Restronguet Point Road (Feock)	PROW	Reported to Cormac, added to their maintenance list FPC to re-site

17/09/2015	Broken footpath signpost 39/3 at junction with road at Higher Trevilla (Feock)	PROW	Reported to Cormac, added to their maintenance list
21/10/2015	Rocky Lane - Tallacks Creek footpath 24/2, fingerpost has rotted and broken	PROW	Reported to Cormac, added to their maintenance list
21/10/2015	Tallacks Valley footpath 28/1, fingerpost has rotted and broken	PROW	Reported to Cormac, added to their maintenance list FPC to re-site
21/10/2015	Boxheater - Higher Trevilla footpath 51/1, fingerpost has rotted and broken	PROW	Reported to Cormac, added to their maintenance list
21/10/2015	Footpath 28 Tallack's Valley, 3 stiles along this route are substandard and require improvement	PROW	Reported to Cormac, added to their maintenance list
27/11/2015	Footpath/waymark signs required junction of FP 19/2 and 21/1 at Lower Tresithick	PROW	Parish Clerk sourcing additional waymarkers
27/11/2015	Footpath/waymark signs required junction of FP 22/1, 21/2 and 21/3 at Lower Tresithick	PROW	Parish Clerk sourcing additional waymarkers
27/11/2015	Footpath 27, bottom two steps are broken, down into gorse field (from Point Road entrance)	PROW	Reported to Cormac, will be repaired urgently, sand bags placed as makeshift step and warning notice displayed <b>REPAIR NOW COMPLETED BY CORMAC</b> Pallet used to stop cattle getting out at bottom of steps
03/10/16	Footpath sign missing at Quenchwell (rotted out and is lying beside the road on the verge)	PROW	FPC to re-site
26/10/16	305/39/4 and 305/40/1 – need better signage	PROW	Waymarkers to be installed